

Remarks:

Reopen boiler @ Center Green Hall. (X)

Run 1/2" Pinned Brains (couple between T's + downsize)
 Dattall Passed - Re - Passed Aug 29/93. Re

INSPECTED	CONDITION	INSPECTED	CONDITION	DATE OF INSPECTION	
Front Yard		Insulation	(1) Ok - from top	1. Frame Bit (X)	
R. Side Yard	Fully to be 1/2"	Rafters	X 1x st. used.	2. July 18/2012	
L. Side Yard	@ R.T. Drops.	Roofing	(2) Metal flashing	3. July 18/2012	
Rear Yard	Back entry stop	Chimney	baton 1" of deck	4.	
Excavation		Fireplace	Re/Vapor barrier	DATE OF INSPECTION	
Footings	Not Comp	Stucco Lath	remit work stone	1. Frame Bit (X)	
Foundation Walls		Plaster Lath	(4) Brk. remove 10"	2. Oct 18/2012	
Columns		Exterior Finish	Chimney	3.	
Beams		Plaster	(5) Gut. stone steps.	4.	
Floor Joists		Stairs	remit.	5.	
Ceiling Joists		Exits		6.	
Bridging		Eav. Tr. & Down Spout		7.	
Headers & Trimmers		Furnace Room		8.	
Sub Floors		Toilet Clearance		Bldg. complete? 1/1/9	
Studding		Attic Trap		Occupied 1/1/9	
Bracing		Louvres		Frame 1/1/9	
Sheathing		Bathroom Vent		Frame 1/1/9	
Fire Stop				Building Inspector	

Building Inspector

OVER