



West Coast
Tank Recovery

4455 Nottingham Rd. North Vancouver BC V7K 2N4

w: wctankrecovery.net

p: 604.628.8786

OIL TANK INSPECTION CERTIFICATE

May 26th 2016

Dax Eliot
3050 Godwin Ave.
Burnaby, BC
V5G 4M4

To Dax Eliot:

We have performed a metal detection scan in available areas using a Fisher TW6 M-Scope and Schonstedt GA92-XT for an underground heating Oil Tank at the above address.

No visual signs of fill or vent pipes were found on the property.

Due to the results of the scan which may have included probing and exploratory digging, we are confident that there is no underground heating Oil Tank in areas that were available to be scanned at the above address.

Respectfully submitted,

Martin Wouters
President, WCTR

Disclaimer

As with any technical equipment or precision devices, results are rarely 100% conclusive. West Coast Tank Recovery Incorporated will not accept in any way whatsoever any liability, costs, lawsuits and or court actions for the future discovery of any underground storage tanks, including but not limited to underground storage tanks found under the original structure, additions added to the original structure, under storage sheds or detached buildings, vehicles, under swimming pools, concreted walkways, driveways or slabs, especially ones which contain rebar or any other metal construction materials, under trees, plants, shrubs, vegetation, patios or decks.